

CENTRAL SACRAMENTO AREA FACT Sheet Site 72.2

Critical Levee Erosion Site

Emergency Levee Repairs

Location

River: Sacramento River

River Mile: 72.2 Latitude/Longitude:

38.698187/-121.631329

Nearest Impact Area:

Woodland
County: Yolo
Bank: Right

Type of Damage

Bank erosion

Length of Repair

1,728 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

U.S. Army Corps of Engineers

For further information, please contact:

Stan Wallin Project Manager U.S. Army Corps of Engineers (916) 557-5225

Stan.J.Wallin@spk01.usace.army.mil

